
MULTIPLE CHOICE. Choose the one alternative that best completes the statement or answers the question.

- 1) Technician A says that worn flywheels should always be replaced. Technician B says that some worn flywheels can be resurfaced. Which technician is correct?
 - A) Technician A only
 - B) Technician B only
 - C) Both technicians
 - D) Neither technician
- 2) Where is the clutch pedal free play adjustment made?



1) _____



- A) A
- B)B
- C) C
- D) D
- 3) Technician A replaces the clutch release bearing as part of any routine clutch service. Technician
 B says that bellhousing bore misalignment may be corrected by using offset dowels. Which technician is correct?
 - A) Technician A only
 - B) Technician B only
 - C) Both technicians
 - D) Neither technician

4) When measuring crankshaft end play, a maximum of is allowed.	4)
A) 0.0005 inch	,
B) 0.25 mm	
C) 0.002 inch	
D) 0.05 mm	
_ /	
5) A squeal is heard as the clutch pedal is depressed about one inch. This is probably caused by a	5)
A) Defective or were release (throweut) bearing	
A) Defective or worn release (throwout) bearing B) Worn clutch disc	
C) Weak pressure plate	
D) Worn pilot bearing	
6) A clutch disc has measured 0.020 rivet head depth. According to the text what should the	6)
technician do?	
A) Resurface the clutch disc	
B) Replace the clutch disc	
C) Sand the disc with 80 grit sandpaper	
D) Replace the flywheel	
7) Clutch chatter can be caused by	7)
A) Grease or oil on the clutch facing	
B) Broken engine mounts	
C) Low hydraulic fluid level	
D) Too little free play in the clutch pedal	
	-
8) A transmission is hard to shift into first gear and cannot be shifted into reverse at all. What could	8)
be the cause?	
A) A loose clutch pedal pad	
B) Excessive clutch pedal free-play	
C) Not enough clutch pedal free-play	
D) Bad U-joints	
9) A cable-operated clutch is being adjusted. Technician A says that free travel is measured at the	9)
clutch pedal and should be between 3/4 and 1 inch (19 to 25 mm). Technician B says that the	
clutch spin-down time should be less than two seconds. Which technician is correct?	
A) Technician A only	
B) Technician B only	
C) Both technicians	
D) Neither technician	
10) A clutch disc is being installed. Technician A says that the damper assembly of the clutch disc	10)
normally faces the pressure plate. Technician B says that the disc splines should be lightly	
lubricated. Which technician is correct?	
A) Technician A only	
B) Technician B only	
C) Both technicians	
D) Neither technician	

Answer Key

Testname: MDA8_5A

- 1) B
 - Page Ref: 90
- 2) B
 - Page Ref: 87
- 3) C
 - Page Ref: 93-94
- 4) B
 - Page Ref: 91
- 5) A
- Page Ref: 89
- 6) B
- Page Ref: 91
- 7) A
 - Page Ref: 90, 94
- 8) B
 - Page Ref: 86, 88
- 9) A
 - Page Ref: 86, 88
- 10) C
 - Page Ref: 94