

**Wheels:** William says in an e-mail, “I have a 1995 Pontiac Transport with 85,000 miles. Most of the driving has been interstate. It has a 3800 engine. It is starting to rumble when shifting into reverse, either standing still or moving. Is it in need of an overhaul? Otherwise, everything works perfectly.”

**Halderman:** From the description, it sounds as if the problem could be in the exhaust system or engine mount area causing a vibration whenever in reverse. I suggest you see an experienced service technician for an opinion before having the transmission checked.

