

Wheels: JS writes, "I have a 1990 Chevrolet pickup with four-wheel drive. When the weather starts getting colder, the power steering will not turn right unless I let it warm up for a couple of minutes. It will turn left OK. I don't have the trouble in warm weather. Can the cylinder cause this or is in the gear box. It is OK after a few minutes."

Halderman: The problem is usually due to the lack of proper sealing in the steering gear itself. Flushing the power steering fluid and using GM cold climate fluid has been found to solve this concern in most cases. If this procedure does not work, then a new steering gear assembly will be necessary.

