

Wheels: An e-mail from David says, “In reference to your June 26 column concerning a man named Wayne, I have a 1998 Volkswagen New Beetle that had the same problems with the AM radio that Wayne had. I had all the same fixes that Wayne had on his radio with no success. The dealer finally ran a new antenna cable in a new location from the antenna to the radio. It has worked perfectly since.”

Halderman: As I stated in the original column, a lack of proper reception on AM only is usually due to an antenna problem.

