

Wheels: An e-mail from Wally says, "I have a 1992 Chevy Silverado 1500 pickup. The problem I experienced is that the electronic heater control display went black. At first I unplugged the wires from the back and there was power, then it quit all together. I spent \$200 for a heater control and it is still black. What is the problem? The fuse is good. Help!"

Halderman: I checked the files at the international automotive technicians network (www.iatn.net) and I found one reference to a problem exactly as you described. It turned out to be a loose ground connection at a connector under the dash behind the ash tray. I suggest that you check that out and see if that takes care of your problem.

