

Wheels: A reader writes, “My 1996 Buick Riviera taillights and instrument panel lights are not working. The fuses were replaced and new bulbs put in, but still nothing. Is this a wiring problem? Any information would be appreciated.”

Halderman: The electrical current for the dash lights are routed through the dimmer module, which could be the cause of the problem. I checked service information and, while both problems are lighting related, there does not appear to be a common connection. The taillights are powered by the turn-hazard switch, which could be defective. I suggest that you take the car to a professional service technician for a diagnostic test.

