

**Wheels:** A letter from Ken of Vandalia says, “I hope you can help me with a problem I am having with my 1997 LeSabre Limited. It has an electronic climate control system with individual controls for both the driver and passenger. When the heater is on, heat comes out the driver’s side but only cold air from the passenger side. It would appear there is a louver that is not being activated. I am told that this louver is controlled by an electronic module. If you would be so kind, I would like to have the identification and location of this item or any other component you might consider suspect.”

**Halderman:** I consulted the service manual and there may be a diagnostic trouble code set if the right side door (louver) is out-of-range. It requires the use of a Tech 2 scan tool (or similar) to retrieve the codes. I would suggest that this be your first step to avoid replacing a part that may not correct your problem. The service manual also states: “check door actuator for proper mounting, broken components or missing/nonattached linkage rods. Repair as necessary.”  
I hope this helps.

