

**Wheels:** Rick says, “We own a 1999 Chevy Malibu LS V-6 with 68,000 miles. About a year ago, the HVAC fan switch quit working on the first and second fan speed settings. It now only works on the third through fifth fan speeds. I have replaced the switch in the instrument panel, and checked all relays and fuses in the 3 relay/circuit boards with no success. Any ideas on where to go next?”

**Halderman:** The problem is most likely a defective blower motor resistor assembly located downstream from the blower motor. It has five wires and, if one of the four resistors failed (blown open), it would match your problem exactly.

