

Wheels: An e-mail from Phoenix asks, “Our daughter’s 1990 Accord interior fan has quit working. At first it was sporadic in operation. It has now quit completely. Given the 106 degree weather we had yesterday, repair seems crucial! My husband has checked the fuse which seems fine – any other ideas?”

Halderman: There are three basic components included in the blower motor circuit:

1. The blower motor
2. The blower motor relay (a likely cause because you lost all speeds and not just the low or high speeds)
3. The resistor pack

Ask a qualified service technician for help because a proper diagnosis can keep you from replacing unnecessary parts.

