
MIII TIPI E CHOICE	Choose the one alternative that best completes the statement or answers the questi	On
MULTIFLE CHOICE.	Choose the one alternative that best completes the statement of answers the questi	on.

- 1) _____ 1) The top of a tire is tilted out when viewed from the front. This is considered to be _____.
 - A) positive camber
 - B) negative camber
 - C) positive caster
 - D) negative toe
- 2) What alignment angle is shown in this drawing?






- A) Positive camber
- B) Positive caster
- C) Positive toe
- D) Negative camber
- 3) A vehicle will pull to the side with the least positive caster.



- A) True
- B) False
- 4) What alignment angle is shown here?





- A) Toe in
- B) Toe out
- C) Camber
- D) Caster

5) What term refers to the distance between a line through the steering axis and the centerline of		
the wheel at the contact point with the road surface?		
A) Scrub radius		
B) Toe-out on turns		
C) SAI		
D) Included angle		
6) Many manufacturers specify some degree of toe.		
A) positive		
B) negative		
C) zero		
D) none of these		
7) Excessive negative camber will cause which of the following?		
A) Inner tire wear		
B) Excessive wheel bearing loading		
C) Improper handling		
D) All of these are correct.		
8) Which angle, if unequal from side to side, is most likely to cause a pull or drift?	8)	
A) Camber		
B) TOOT		
C) Toe		
D) None of these		
9) What is the maximum amount generally allowed for camber side-to-side difference?	9)	
A) 1/2 degree		
B) 0 degrees		
C) 1 degree		
D) None of these are correct.		
(0) If the top of the steering axis is tilted 2 degrees toward the rear of the vehicle, this is called	10)	
A) positive camber		
B) negative camber		
C) negative caster		

D) positive caster

Answer Key

Testname: AT6_124A

- 1) A Page Ref: 1525
- 2) A Page Ref: 1526
- 3) A Page Ref: 1528
- 4) A Page Ref: 1529
- 5) A Page Ref: 1532
- 6) A Page Ref: 1530
- 7) D Page Ref: 1524
- 8) A Page Ref: 1525
- 9) A Page Ref: 1525
- 10) D Page Ref: 1527