Automotive Engine Performance, 5th Edition Quiz 33A

Name\_\_\_\_\_

MULTIPLE CHOICE.	Choose the one alternative that best completes the statement or answers the question.
	choose the one alternative that best completes the suitement of anothers the question

1) A paper test can be used to check for a possible problem with	1)
A) The ignition system (bad spark plug wire)	
B) A faulty injector on a multiport fuel injected engine	
C) A burned valve	
D) All of the above	
2) Which item is NOT important to know before starting the diagnosis of an engine performance	2)
problem?	
A) List of previous repairs	
B) The brand of engine oil used	
C) The type of gasoline used	
D) The temperature of the engine when the problem occurs	
3) Technician A says that when checking engine oil, it is normal for the oil to catch fire if lit by a	3)
match. Technician B says that if the oil on the dipstick catches fire when lit is a sign of fuel in the	
oil. Which technician is correct?	
A) Technician A only	
B) Technician B only	
C) Both technicians	
D) Neither technician	
4) A freeze frame is stored when a type DTC is set.	4)
A) A or B	-/
B) A or C	
C) B or C	
D) C or D	
5) The preferred method to clear diagnostic trouble codes (DTCs) is to	5)
A) Disconnect the negative battery cable for 10 seconds	
B) Use a scan tool	
C) Remove the computer (PCM) power feed fuse	
D) Cycle the ignition key on and off 40 times	
6) Which diagnostic step is the most important aspect of diagnosis?	6)
A) Visual inspection	
B) Verify the problem	
C) Retrieve the trouble codes	
D) Check the service bulletins	
7) Type DTCs are set by non-emission related diagnostic tests.	7)
A) A or B	
B) A and C	
C) B and C	
D) C and D	

8) Technician A says that water floats to the top of fuel in the tank. Technician B says that water is 8) \_\_\_\_\_ more likely to be drawn into the system when the fuel level is low. Which technician is correct? A) Technician A only B) Technician B only C) Both technicians D) Neither technician 9) Technician A says that most TSBs involve a specific stored DTC. Technician B says that the ECT 9) \_\_\_\_\_ and IAT reading should be close to the same temperature after the vehicle sits for several hours. Which technician is correct? A) Technician A only B) Technician B only C) Both technicians D) Neither technician 10) All these actions involve verifying the problem EXCEPT \_\_\_\_\_. 10) \_\_\_\_\_ A) Look for aftermarket parts B) Determine the temperature the when problem occurred

C) Check the MIL D) Look for TSBs

2

Answer Key Testname: ENGINEPERF5\_33A

1) D Page Ref: 526 2) B Page Ref: 523-525 3) B Page Ref: 525 4) A Page Ref: 538 5) B Page Ref: 531 6) A Page Ref: 525 7) D Page Ref: 538 8) B Page Ref: 526 9) C Page Ref: 527-528 10) D Page Ref: 523-525