


Name \_\_\_\_\_

**MULTIPLE CHOICE. Choose the one alternative that best completes the statement or answers the question.**

- 1) Why should red assembly lube be avoided? 1) \_\_\_\_\_
  - A) Can harm friction disks
  - B) Too slippery
  - C) Clogs filters
  - D) Looks like an ATF leak when it melts
  
- 2) Clutch pack clearance may be adjusted by all of the following EXCEPT \_\_\_\_\_. 2) \_\_\_\_\_
  - A) Adjustable O-ring
  - B) Selective size snap ring
  - C) Selective apply ring
  - D) Different thicknesses pressure plates
  
- 3) A broken flex plate may be caused by \_\_\_\_\_. 3) \_\_\_\_\_
  - A) Damaged engine mounts
  - B) A bent driveshaft
  - C) Missing engine alignment dowels
  - D) Missing pump dowels
  
- 4) Technician A says that if a tapered roller bearing cup is worn and needs to be replaced, the rest of the bearing parts can be reused. Technician B says that if a tapered bearing is to be reused it must be installed in its original position. Which technician is correct? 4) \_\_\_\_\_
  - A) Technician A only
  - B) Technician B only
  - C) Both technicians
  - D) Neither technician
  
- 5) Clutch pack clearance can be checked using \_\_\_\_\_. 5) \_\_\_\_\_
  - A) A feeler gauge
  - B) A dial indicator
  - C) Either A or B depending on the clutch and access to measuring the clearance
  - D) Both methods should be used to insure accuracy
  
- 6) When installing an uncut Teflon sealing ring, what does the installation tool do? 6) \_\_\_\_\_
  - A) It cuts, then re-welds the ring ends
  - B) It stretches the ring
  - C) It shrinks the ring so it will pop into place
  - D) Allows installing two rings at a time

- 7) Two technicians are discussing discolored areas found in a band's friction materials. Technician A says that you should replace the band. Technician B says that you should soak a new band in ATF. Which technician is correct? 7) \_\_\_\_\_
- A) Technician A only
  - B) Technician B only
  - C) Both technicians
  - D) Neither technician

- 8) What test is being performed in this illustration? 8) \_\_\_\_\_



- A) Transmission end-play
- B) Bell housing runout
- C) Clutch spline clearance
- D) Stator mount clearance

- 9) A radial needle bearing is commonly called a \_\_\_\_\_. 9) \_\_\_\_\_
- A) Bushing
  - B) Torrington
  - C) Bearing
  - D) Cup

- 10) Technician A says that during an overhaul of a transaxle, the differential should be disassembled and inspected. Technician B says that the differential is not a part of the automatic transaxle. Which technician is correct? 10) \_\_\_\_\_
- A) Technician A only
  - B) Technician B only
  - C) Both technicians
  - D) Neither technician

## Answer Key

Testname: ATT7\_17A

1) D

Page Ref: 261

2) A

Page Ref: 257

3) C

Page Ref: 262

4) B

Page Ref: 247

5) C

Page Ref: 257

6) B

Page Ref: 251

7) C

Page Ref: 248-249

8) A

Page Ref: 261

9) B

Page Ref: 246

10) A

Page Ref: 261