


Name _____

MULTIPLE CHOICE. Choose the one alternative that best completes the statement or answers the question.

- 1) Why should red assembly lube be avoided? 1) _____
A) Can harm friction disks
B) Too slippery
C) Clogs filters
D) Looks like an ATF leak when it melts

- 2) A radial needle bearing is commonly called a _____. 2) _____
A) Bushing
B) Torrington
C) Bearing
D) Cup

- 3) What measurement is being made in this illustration? 3) _____



- A) Clutch retainer ring torque
B) Clutch pack clearance
C) Clutch lining thickness
D) None of these

- 4) Technician A says that during an overhaul of a transaxle, the differential should be disassembled and inspected. Technician B says that the differential is not a part of the automatic transaxle. Which technician is correct? 4) _____
A) Technician A only
B) Technician B only
C) Both technicians
D) Neither technician

- 5) When disassembling a clutch pack a _____ is usually a required tool. 5) _____
A) Small hammer
B) Chisel
C) Spring compressor
D) Leather glove
- 6) When installing an uncut Teflon sealing ring, what does the installation tool do? 6) _____
A) It cuts, then re-welds the ring ends
B) It stretches the ring
C) It shrinks the ring so it will pop into place
D) Allows installing two rings at a time
- 7) Technician A says that an end play check should be performed to make sure that the unit has been correctly assembled. Technician B says that the end play check can be used to check for proper internal clearances. Which technician is correct? 7) _____
A) Technician A only
B) Technician B only
C) Both technicians
D) Neither technician
- 8) When servicing a clutch assembly, what special tool is required? 8) _____
A) A piston ring clamp
B) A clutch disc alignment tool
C) A spring compressor
D) A needle guide
- 9) What should be done when installing a transmission/transaxle? 9) _____
A) Make sure that the transmission alignment dowels are installed
B) Connect the cooler lines and tighten them to the correct torque
C) Check the linkage for proper adjustment so that the shift interlock works correctly and the PRNDL is aligned with the transmission range switch
D) All of the above
- 10) Two technicians are discussing discolored areas found in a band's friction materials. Technician A says that you should replace the band. Technician B says that you should soak a new band in ATF. Which technician is correct? 10) _____
A) Technician A only
B) Technician B only
C) Both technicians
D) Neither technician

Answer Key

Testname: ATT7_17B

1) D

Page Ref: 261

2) B

Page Ref: 246

3) B

Page Ref: 257

4) A

Page Ref: 261

5) C

Page Ref: 256

6) B

Page Ref: 251

7) C

Page Ref: 260

8) C

Page Ref: 255

9) D

Page Ref: 263

10) C

Page Ref: 248-249