

Name _____

MULTIPLE CHOICE. Choose the one alternative that best completes the statement or answers the question.

- 1) Excessive negative camber will cause which of the following? 1) _____
 - A) Inner tire wear
 - B) Excessive wheel bearing loading
 - C) Improper handling
 - D) All of these are correct

- 2) A vehicle will pull to the side with the most (positive) toe. 2) _____
 - A) True
 - B) False

- 3) A steering dampener may be needed to reduce shimmy on vehicles that have a high positive _____ 3) _____
 - A) camber
 - B) caster
 - C) toe
 - D) included angle

- 4) Which alignment angle is adjustable on all vehicles? 4) _____
 - A) Camber
 - B) Caster
 - C) Toe
 - D) SAI

- 5) If REAR toe is uneven, the vehicle will pull to the side with the most toe-in. 5) _____
 - A) True
 - B) False

- 6) Included angle is _____. 6) _____
 - A) SAI + caster
 - B) camber + caster
 - C) camber + SAI
 - D) toe + camber

- 7) Which of these statements is TRUE regarding scrub radius? 7) _____
 - A) It cannot be adjusted.
 - B) It can be measured.
 - C) Both A and B
 - D) Neither A nor B

- 8) Two technicians are discussing scrub radius. Technician A says that scrub radius cannot be measured. Technician B says that scrub radius cannot be adjusted. Which technician is correct? 8) _____
- A) Technician A only
 - B) Technician B only
 - C) Both technicians A and B
 - D) Neither technician A nor B
- 9) A vehicle will pull to the side with the least positive caster. 9) _____
- A) True
 - B) False
- 10) All of these symptoms may be corrected by an alignment EXCEPT _____. 10) _____
- A) wander
 - B) wheel tramp
 - C) pulling to one side
 - D) drifting to one side

Answer Key

Testname: CHASSIS8_35B

1) D

Page Ref: 579

2) B

Page Ref: 583

3) B

Page Ref: 580

4) C

Page Ref: 583

5) A

Page Ref: 583

6) C

Page Ref: 586

7) A

Page Ref: 587

8) C

Page Ref: 587

9) A

Page Ref: 581

10) B

Page Ref: 576-577