
Service Information, Tools, And Safety

Chapter 1



ACROSS

___ strength is the maximum stress used under tension (lengthwise force) without causing failure of the fastener. _ codes are usually located on Powertrain Control Modules (PCMs) or other controllers. 8 Service technicians working under a vehicle should wear a ___ cap to protect the head against under-vehicle objects and the pads of the lift. 13 The strength or classification of a bolt is called the _ _____ electric vehicles use a high-voltage battery pack and an electric motor(s) to help propel the vehicle. _____ service bulletins, often abbreviated Tsbs, 18 __ sometimes called technical service information bulletins (TSIB), are issued by the vehicle manufacturer to notify service technicians of a problem and include the necessary corrective action. 19 A _____ dioxide fire extinguisher is good for almost any type of fire, especially Class B and Class C materials. ____ rating (GVWR) is the 20 maximum (upper limit) weight of a vehicle as specified by the

DOWN

1	Service technicians should wear protective
	equipment (ppe) to prevent personal injury.
2	a can occur when either the manufacturer or the
	National Highway Traffic Safety Administration (NHTSA)
	determines there is a concern.
4	A is a short rod with threads on both ends.
5	Abbreviation for vehicle identification number.
6	a is typically issued when a manufacturer wants
	to improve a product's performance or increase the
	customer's satisfaction.
9	Most grinders are equipped with a grinder wheel
	(stone) on one end and a wire brush wheel on the other end
10	numbers can be used to identify the part and
	check dimensions such as the cubic inch displacement and
	other information, such as the year of manufacture.
11	Abbreviation for vehicle emissions control information.
12	The size of a bolt is specified by the letter M
	followed by the diameter in millimeters (mm) across the
	outside (crest) of the threads.
14	Most of the threaded fasteners used on vehicles are
15	are often used under cap screw heads and under
	nuts.
17	A or campaign is issued by a vehicle manufacture
	and a notice is sent to all owners in the event of a safety-
	related fault or concorn



vehicle manufacturer.