


Circuit Testers and Digital Meters

Chapter 3



www.CrosswordWeaver.com

ACROSS

- 1 ____ means 1,000.
- 7 ____ means over limit or overload.
- 9 Abbreviation for digital multimeter.
- 11 An _____ measures the resistance in ohms of a component or circuit section when no current is flowing through the circuit.
- 12 The ____ has several categories of voltage standards for meter and meter leads.
- 13 A ____ _____ is an electric device that lights up a red LED if the probe is touched to battery voltage.
- 14 ____ means 1,000,000
- 15 An _____ measures the flow of current through a complete circuit in units of amperes.
- 16 A _____ will light up a red LED if the probe is touched to battery voltage. If the probe is touched to ground, a green LED lights.

DOWN

- 2 _____ do not make physical contact with the circuit.
- 3 _____ is the largest allowable error that will occur under specific operating conditions.
- 4 An AC/DC _____-_____ multimeter is a useful meter for automotive diagnostic work.
- 5 _____ clips at the ends allow the fused jumper wire to be clipped to a ground or power source while the other end is attached to the power side or ground side of the unit being tested.
- 6 The abbreviation RMS stands for ____-_____-_____ and for a true sine wave is the same for average reading meters.
- 8 AC stands for _____ current or voltage.
- 10 ____ means 1/1,000