Automotive Technology 6th Edition
Chapter 24 - Intake and Exhaust Systems
Quiz 24A

A) bolt hole sizesB) slight warpageC) misaligned flanges

D) cracks

ame		
MULTIPLE CHOICE. Choose the one alternative that best completes the statement or answers the question.		
 Technician A says that exhaust manifolds can be made from hard plastic or aluminum. Technician B says that many intake manifolds have an EGR valve that regulates the amount of recirculated exhaust that enters the engine in order to increase NO_X emissions. Who is right? A) Technician A only B) Technician B only C) Both technicians 	1)	
D) Neither technician		
2) Why do many port fuel injected engines use long intake runners? A) To reduce exhaust emissions	2)	
B) To heat the incoming air C) To increase high RPM power D) To increase low RPM torque		
3) Why is the catalytic converter places as close to the engine as possible?	3)	
A) For easier access when working on the engineB) So the heat can help the converter work most efficientlyC) To allow the exhaust pipes from the catalytic converter rearward to be a long as possibleD) To prevent the heat from the exhaust system moving upward toward the floor of the vehicle		
4) A cracked exhaust manifold can cause false readings from which of these engine sensors?	4)	
A) Oxygen sensorB) Coolant temperature sensorC) Intake air temperature sensorD) Exhaust temperature sensor		
5) Some vehicles have no exhaust manifold and the catalytic converter is attached directly to the	5)	
A) exhaust down pipe B) cylinder head C) engine block D) muffler		
6) Exhaust manifold gaskets are used to compensate for in the exhaust manifold.	6)	

7) Technician A says that some intake manifolds are plastic. Technician B says that some intake manifolds are constructed in two parts or sections: upper and lower. Which technician is correct? A) Technician A only B) Technician B only C) Both technicians D) Neither technician	7)
8) Technician A says that a cracked exhaust manifold can affect engine operation. Technician B says that a leaking lower intake manifold gasket could cause a vacuum leak. Which technician is correct? A) Technician A only B) Technician B only C) Both technicians D) Neither technician	8)
9) Air filters can remove particles and dirt as small as	9)
A) 5 to 10 microns	- /
B) 10 to 25 microns	
C) 30 to 40 microns	
D) 40 to 50 microns	
10) Technician A says that a cracked exhaust manifold can affect engine operation. Technician B says that a leaking lower intake manifold gasket could cause a vacuum leak. Which technician is correct?	10)
A) Technician A only	
B) Technician B only	
C) Both technicians	

D) Neither technician

Answer Key

Testname: AT6_24A

1) D

Page Ref: 240-241

2) D

Page Ref: 238

3) B

Page Ref: 243

4) A

Page Ref: 242

5) B

Page Ref: 243

6) B

Page Ref: 242

7) C

Page Ref: 239

8) C

Page Ref: 239

9) B

Page Ref: 236

10) C

Page Ref: 239, 242