

Answer Key

1. gap (or clearance)
2. valve sticking
3. excessive wear
4. solvent
5. small hole gauge
6. micrometer
7. 0.314
8. valve stem
9. subtract
10. 0.002 (two-thousandths)