Automotive Electrical and Engine Performance, 8th Edition Quiz 44A		
Name		
MULTIPLE CHOICE. Choose the one alternative that best completes the statement or answers the question.		
 Technician A says that knowing if there are any stored diagnostic trouble codes (DTCs) may be helpful when checking for related technical service bulletins (TSBs). Technician B says that only a factory scan tool should be used to retrieve DTCs. Which technician is correct? A) Technician A only B) Technician B only C) Both technicians D) Neither technician 	1)	
 2) Technician A says that when checking engine oil, it is normal for the oil to catch fire if lit by a match. Technician B says that oil on the dipstick that catches fire when lit is a sign of fuel in the oil. Which technician is correct? A) Technician A only B) Technician B only C) Both technicians D) Neither technician 	2)	
 3) When should DTCs be cleared? A) After the problem has been verified B) After pinpointing a problem cylinder C) After consulting TSBs D) After the repair has been verified 	3)	
 4) Technician A uses a scan tool to clear stored DTCs. Technician B says that clearing DTCs will also clear all of the noncontinuous OBD-II monitors. Which technician is correct? A) Technician A only B) Technician B only C) Both technicians D) Neither technician 	4)	
 5) How many times must the ignition switch be cycled to put a Chrysler computer in self-test mode? A) Two B) Five C) Eight D) One 	5)	
6) Technician A says that it is a good idea to perform a test drive before attempting repairs. Technician B says that its a good idea to let the customer accompany the technician on the test drive. Which technician is correct?	6)	

A) Technician A only B) Technician B only C) Both technicians

D) Neither technician

7) Technician A says that most TSBs involve a specific stored DTC. Technician B says that the ECT	7)
and IAT reading should be close to the same temperature after the vehicle sits for several hours.	
Which technician is correct?	
A) Technician A only	
B) Technician B only	
C) Both technicians	
D) Neither technician	
8) What is the factory scan tool for Chrysler brand vehicles equipped with CAN?	8)
A) Star Scan	·
B) Tech 2	
C) NGS	
D) Master Tech	
9) All these actions involve verifying the problem EXCEPT	9)
A) Look for aftermarket parts	, <u> </u>
B) Determine the temperature the when problem occurred	
C) Check the MIL	
D) Look for TSBs	
10) Technician A says that generic scan tools must be able to read all generic OBD-II codes.	10)
Technician B says that all generic scan tools must be able to read manufacturer OBD-II trouble	,
codes. Which technician is correct?	
A) Technician A only	
B) Technician B only	
C) Both technicians	

D) Neither technician

Answer Key

Testname: AEEP8_44A

- 1) A Page Ref: 639, 641
- 2) B Page Ref: 637
- 3) D Page Ref: 640
- 4) C
- Page Ref: 640, 651 5) A
- Page Ref: 643
- 6) C Page Ref: 637
- 7) C Page Ref: 639
- 8) A Page Ref: 641
- 9) D Page Ref: 635-637
- 10) A Page Ref: 641