Automotive Engines 10th

Quiz 21A


MULTIPLE CHOICE. Choose the one alternative that best completes the statement or answers the question.

 Technician A says that a clicking sound indicates a loose torque converter. Technician B says that many engine-related problems make a characteristic noise. Which technician is correct? A) Technician A only B) Technician B only C) Both technicians A and B D) Neither technician A nor B 	1.	
2. Which of these smoke types indicates oil being burned in the combustion chamber?	2.	
A) Blue		
B) Black		
C) White		
D) Grey		
3. The pressure measured in the exhaust system should not be more than PSI.	3.	
A) 1.5		
B) 2.5		
C) 14.7 D) 21		
D) 21		
4. A restricted exhaust system will cause manifold vacuum toas pressure in the exhaust	4.	
system		
A) increase; increases		
B) decrease; decreases		
C) decrease; increases D) None of these are correct		
D) None of these are correct		
5. A smoothly operating engine depends on	5.	
A) high compression on most cylinders		
B) equal compression between cylinders		
C) cylinder compression levels above 100 psi (700 kPa) and within 70 PSI (500 kPa) of each		
other		
D) compression levels below 100 psi (700 kPa) on most cylinders		
	_	
6. The low oil pressure warning light usually comes on	6.	
A) when an oil change is required		
B) when oil pressure drops dangerously low (4 to 7 psi)		
C) when the oil filter bypass valve opens D) when the oil filter anti-drain back valve opens		
D) when the on liner and-drain back valve opens		
7. Most mechanical engine problems are caused by which of these?	7.	
A) Overcooling	7.	
B) Overheating		
C) Fuel Loss		
D) High RPM		
, U		

- 8. A good engine should produce how much compression during a running (dynamic) compression test at idle?
- 8. ____

9.

- A) 150-200 PSI
- B) 100-150 PSI
- C) 60-90 PSI
- D) 30-60 PSI
- 9. The vacuum reading shown was taken from an engine at idle speed. The reading indicates that



- A) the timing is retarded
- B) the engine is in good mechanical condition
- C) a valve is out of adjustment
- D) the idle speed is too low
- 10. Technician A says that a compression test can be used to test the condition of connecting rods. Technician B says that a cylinder leakage test fills the cylinder with compressed air, and the gauge indicates the percentage of leakage. Which technician is correct?
- 10. ____

- A) Technician A only
- B) Technician B only
- C) Both technicians A and B
- D) Neither technician A nor B

Answer Key

Testname: ENGINES 10 21A

- 1. B
 - Page Ref: 289
- 2. A
 - Page Ref: 285
- 3. B
 - Page Ref: 299
- 4. C
 - Page Ref: 299
- 5 F
 - Page Ref: 291
- 6. B
 - Page Ref: 300
- 7. B
 - Page Ref: 286
- 8. C
 - Page Ref: 294
- 9. B
 - Page Ref: 297
- 10. B
 - Page Ref: 291; 295