
Transmission Condition Diagnosis

Chapter 15



http://jameshalderman.com

ACROSS

more than one brand of vehicle. 3 Some vehicles include a code for _____ index, also called transmission adapt pressure (TAP) or clutch fill volume index. 6 The vehicle DTCs and data can be acquired by looking at the _____ (generic) part of the PCM and does not need to have the vehicle information entered into the 12 Another name for Powertrain Control Module (PCM) is ____ module. 14 Bearing noise, often described as a _____, is caused by damage, pits, or scoring that makes the surface rough. 15 A ____ is used to verify the customer's concern and check the general overall condition of the transmission.

_____ tools are designed to function on

DOWN

2	When a new TCM is installed it is often necessary to	
	perform a	_•
4	One of the roles of the	module is
	to monitor the transmission operation and determine if	
	malfunctions may be occurring.	
5	The three most common sources of transmission noise	
	are bearings, gears, and t	he system.
7	Check for the proper voltage and current of the	
	using a factory or factory-level scan tool.	
8	Some highly	ATF's tend to turn
	light brown after a short period of time and this should	
	not be used as a sign of fluid breakdown.	
9	On a scan tooll, a	pulse width should
	read 1.5 to 3.5 ms.	
10	tools are scan tools required by all	
	dealers that sell and service specific brand vehicles.	
11	On a scan tool, an	oxygen sensor should
	have a voltage varying between 200 and 800 mV.	
13	Honda's factory scan tool is called HDS or	