

Answer Key

1. temperature-sensitive
2. warm up
3. wax
4. cold
5. closed
6. bypass
7. melt
8. expands
9. small piston
10. hot (or warm)