







40 USED VEHICLE AND PRE-DELIVERY INSPECTIONS

FIGURE 40.3 (a) The left side of a lift gate on an SUV shows a wide gap. (b) The right side of the same lift gate on the passenger side shows a very small gap. This shows that this vehicle may have been in an accident and not properly repaired.

(a) (b)

PEARSON Introduction to Automotive Service
James Hallemann, Darrell Decker © 2013 Pearson Higher Education, Inc.
Pearson Prentice Hall - Upper Saddle River, NJ 07458

40 USED VEHICLE AND PRE-DELIVERY INSPECTIONS

FIGURE 40.4 Plastic protective covering is used on all surfaces that may be touched by others during transport from the assembly plant to the selling dealer. This plastic is removed at the dealer before the vehicle is delivered to the customer.

PEARSON Introduction to Automotive Service
James Hallemann, Darrell Decker © 2013 Pearson Higher Education, Inc.
Pearson Prentice Hall - Upper Saddle River, NJ 07458
